



# SAFETY



33% of accidents are apprentices  
1 in 4 fatalities are apprentices

## FALLS

1. Wear Proper PPE (Safety Harness)
2. Use three points of contact while climbing a ladder.
3. Do not over reach, move the ladder for better access.
4. Stay behind safety barriers and away from edges.



## ELECTROCUTION

1. Use proper lock-out-tag-out procedures.
2. Do not work in standing water.
3. Assess your work area and notify management of unsafe conditions.



## STRUCK BY OBJECTS

1. Be cognizant of your surroundings.
2. Wear all PPE (Hard Hat, Safety Glasses, Work Boots)
3. Do not cross danger (RED) or caution (YELLOW) tape without approval.



OSHA has lowered the PEL for Silica from 50 mg/m<sup>3</sup> to 25 mg/m<sup>3</sup>.